




















Kumodes KM043 montāžas instrukcija




 A	 B	 C	 D Ø3,5×15
 E Ø5×11	 F	 G	 H
 J Ø7×50	 K Ø3×20	 L	 M
	 N	 P	 R




1




2




3




4




5




6



7



8



9

